CONTENTS.

PAPERS.

		- Control of the Cont	
NO.	MONTH.	· PAG	E.
483	(July.)	Chimney for the Narragansett Electric Lighting Company, Providence, R. I.	
		JOHN T. HENTHORN	1
		Discussion on Paper No. 483. By Charles E. Emery	7
481	(do.)	The First Trip Through the Big Horn Cañon. E. GILLETTE	8
485	(đo.)	Discussion on Paper No. 444, "Reducing Internal Wastes in the Steam Engine." By Robert H. Thurston.	15
486	(do.)	Discussion on Paper No. 465, "Permanent Effects of Strains on	40
		Metals," By William Metcalf	17
		R. H. THURSTON	17
		J. B. Johnson.	17
400	(4.)	Sections and Mechanical Conditions of Car Wheels,	
487	(do.)	P. H. GRIFFIN	23
		Discussion on Paper No. 487.	
		By George B. Nicholson	39
		P. H. Griffin	39
488	(do.)	A Memoir on Water Meters.	
		John Thomson	40
		Discussion on Paper No. 488.	
		By E. Kuichling	66
489	(do.)	Excessive Rainfalls Considered with Especial Reference to their Occurrence in Populous Districts.	
		R. L. HÖXIE	70
•			
		Discussion on Paper No. 489.	108
			109
		THE PROPERTY AND ADDRESS OF THE PARTY OF THE	110
			110
		George S. Rice	111
		THOMAS C. KEEFER	111
		John F. Barnard111,	113
		E. C. CLARKE	112
		CHARLES LATIMER112, 113,	
		F, Collingwood	112
		J. BLICKENSDERFER113, S. WHINERY	116
490	(do.)	Mountain Railroad Construction. WILLIAM BARCLAY PARSONS	119

NO.	MONTH.	PAC	BE.
491	(August.)	Inland Sewage Disposal, with Special Reference to the East	
		Orange, N. J., Works.	
		C. PH. BASSETT	125
		Discussion on Paper No. 491.	
			146
			148
		George W. Rafter	149
			156
492	(do.)	American Irrigation Engineering.	
	(00.)		161
		Discussion on Paper No. 492.	
			219
			220
			220
		· Control of the cont	220
			221
			222
			222
493	(do.)	Experiments on the Transverse Brenking Strain of Plate Glass	
		G. W. PLYMPTON	223
		Discussion on Paper No. 493.	
		By John C. Trautwine, Jr	226
494	(do.)	A Cheap Covered Reservoir.	
	(mas)		228
		Discussion on Bonon No. 494	
		Discussion on Paper No. 494 By A. FTELEY	230
10=	1.2- >		
495	(do.)	A Diagram, giving by Inspection the Dimensions of Wooden	
		Beams for a given Span and Load.	231
		J. M. MICHAELSON	201
496	(do.)	Advantages of a Longitudinal Bearing System for Railway Tracks.	
		THOMAS C. CLARKE	234
		Discussion on Paper No. 496	
		By WILLIAM P. SHINN	243
		HENRY G. PROUT	244
		J. B. Francis	245
		P. F. Brendlinger	249
		O. CHANUTE	246
		E. E. RUSSELL TRATMAN	246
		James Owen	248
		C. E. GOAD	248
		E. P. NORTH	248
		HUNTER McDonald	249
		J. FOSTER CROWELL	249 250
		T. C. CLARKE	200
497	(September.)		
		10th-13th, 1886.	253
		DESMOND FITZGERALD	200
498	(do.)	Notes on Cements, Mortars and Concretes.	259
		WILLIAM H. GRANT	209

NO.	MONTH.	PA	GE.
	(September.)	Discussion on Paper No. 498,	
		By J. FOSTER CROWELL	279
		JAMES OWEN	279
		CHARLES B. BRUSH	280
		C. H. MYERS	281
		F. Collingwood	281
		A. S. C. WURTELE	282
		D. J. WHITTEMORE	283
		W. W. MACLAY	286
		W. R. HUTTON	287
		A. P. BOLLER	290
		WILLIAM H. GRANT	292
400	12-1		
499	(do.)	Neat Tests vs. Sand Tests for Portland Cement.	005
		S. Bent Russell	295
		Discussion on Paper No. 499.	
		By D. J. WHITTEMORE,	300
		W. W. MACLAY	303
		W. R. HUTTON	303
		S. Bent Russell	304
500	(do.)	The Marent Gulch Viaduct.	
		GEORGE S. MORISON	305
501	(do.)	Right of Way for Railroads.	
		JULIEN A. HALL	313
		Discussion on Paper No. 501.	
			322
		By Robert L. Harris	
		P. F. Brendlinger	324
		C. J. BATES	324
		E. P. NORTH325,	
		CHARLES B. BRUSH	325
		J. FOSTER CROWELL326	
		CHARLES E, EMERY	328
		George R. Hardy	329
		WILLIAM P. SHINN	330
		ROBERT MOORE	332
		George B, Nicholson	333
		FRED BROOKS	334
		JOHN F. WALLACE	334
		H. V. HINCKLEY	337
		C. D. PURDON	339
		JULIEN A. HALL	339
502	(do.)	Discussion on Paper No. 478, The Ravine du Sud.	
002	(00.)	By WILLIAM R. HUTTON	343
		J. FOSTER CROWELL	346
		RUDOLPH HERING	347
***			941
503	(October.)	The American Railroad Viaduct; its Origin and Evolution,	
		J. E. Greiner	349
		Discussion on Paper No. 503,	
		By George S. Morison	360
		G. BOUSCAREN	360
		ROBERT MOORE	360
		E. THACHER	361
		T. C. CLARKE	362
		A, P, BOLLER	362
		J. E. GREINEB	371

NO.	MONTH.		PAGE.
504	(October.)	Screw Steamship and Tow Barge Efficiency in the Northwestern	
		Lakes of America.	
		Joseph R. Oldham	373
		Discussion on Paper No. 504,	
		By Charles E, Emery	385
		*	385
		HERBERT C. FELTON	-
		GEORGE S. MORISON	386
		J. A. OCKERSON	386
		R. H. THURSTON	387
		CHARLES H. HASWELL	390
		J. R. OLDHAM	391
505	(do.)	The Single Trap System of House Drainage.	
		LATHAM ANDERSON	394
		Discussion on Paper No. 505.	
		By Charles B. Brush	407
		LATHAM ANDERSON	408
506	(do.)	The Proposed Lake Erie and Ohio River Ship Canal.	
	(00.)	J. M. GOODWIN	411
		o. m. doopwin	211
		Discussion on Paper No. 506.	
		By E. P. NORTH 410	6, 417
		J. M. GOODWIN410	6, 418
507	1301	On the Straits of Juan de Fuca, Puget Sound, and Government	
001	(do.)	Improvements on the Pacific Coast.	
		BOLTON W. DECOURCY	420
		avada II. aavvantaiiii III.	200
		Discussion on Paper No. 507.	
		By George H. Mendell	434
		B. W. DE COURCY	440
508	(do.)	Some Recent Experiments with Dynamite on an Ocean Bar,	
		O. M. CARTEB	442
		Discussion on Paper No. 508,	
		By Charles B. Brush	446
		F. COLLINGWOOD	446
		A. FTELEY	447
		J. F. Lewis	447
		MILNOB P. PARET	448
		B. W. DECOURCY	449
		L. M. HAUPT	449
		J. F. LE BARON,	450
		S. A. REED	453
		O. M. CARTER	456
		C. Mai Villa Maintenance Control Contr	100
509	(November.)	Stresses in Railway Bridges on Curves.	
	,	WARD BALDWIN	459
		Discussion on Paper No. 509.	
		By WILLIAM SCHERZER	492
		THOMAS H. JOHNSON	493
		E. THACHER	496
		H. B. SEAMAN	498
		WARD BALDWIN,	498
510	(do.)	Dimension Stone Quarrying—The Blasting Process.	
		WILLIAM L. SAUNDERS	501

NO.	MONTH.	Discussion on Paper No. 510.	PAGE.		
	(By L. L. Buck	514		
		M. W. MANSFIELD	515		
		R. C. McCalla, Jr	516		
		W. L. SAUNDERS	517		
511	(do.)	The Brazos River Harbor Improvement. GEORGE Y. WISNER.	519		
		Discussion on Paper No. 511.	010		
		By G. H. MENDELL	537		
		O. H. Ernst	538		
		ARTHUR J. MASON	540		
		L, M. HAUPT	540		
		H. C. RIPLEY	542		
		A. E. KASTL	548		
		R. E. MCMATH	552		
		J. F. LE BARON	552		
		W. R. HUTTON	558		
		GEORGE Y. WISNER	560		
		E, L, Corthell	561		
512	(do.)	Discussion on Paper No. 488-A Memoir on Water Meters.			
		By G. Leverich	563		
513	(December.)	Improvement of the Chaunels at the Entrance to the Harbor of New York.			
		JOSEPH EDWARDS,	573		
514	(do.)	Longitudinals vs. Cross-Ties for Railway Tracks.			
		E, E. RUSSELL TRATMAN	615		
		Discussion on Paper No. 514.			
		By Thomas C. Claree	624		
		J. FOSTER CROWELL	625		
		E. E. R. TRATMAN	627		
515	(do.)	Free Railway Construction vs. Government Controlled and Owned Railways.			
		E. Bates Dorsey	628		
		Discussion on Paper No. 515.			
		Ry Robert Moore	634		
516	(do.)	Discussion on Paper No. 493, on Experiments on the Transverse Strength of Plate Glass.			
		By J. C. TRAUTWINE, JR	635		
		E. R. KELLER	635		
		F. Collingwood	637		
		G. W. PLYMPTON	637		
			001		
517	(do.)	Experimental Determination of the Bolling Friction in Operat- ing the Draw of the Thames River Bridge, together with the Method for Determining Power to Operate Draw-Bridges.			
		A. P. Boller, Jr., and H. J. Schumacher	638		
		Discussion on Paper No. 517.			
		By THEODORE COOPER	653		
		WILLIAM H. BURR	654		
		LEFFERT L. BUCK	657		
		F. W. SKINNER	658		
		W. H. BREITHAUPT	659		
		A. P. Bolleb, Jr., and H. J. Schumacheb	659		

***	MACANINE		
No.	MONTH.		PAGE,
518	(December.)	Red Rock Cantilever Bridge,	
		8, M. Rowe	662
		S. W. ROBINSON	697
		HENRY H. QUIMBY	704
		Discussion on Paper No. 518,	
		By CHARLES MACDONALD	721
		J. F. WALLACE	722
		W. H. BREITHAUPT	722
		EDWIN THACHER,	724
		S. M. Rowe	726
		S. W. ROBINSON	726
		HENRY H OUTSER	792

ERRATA.

By an exchange of tracings in preparing the matter for publication, the long scale to the right on Plates XCIX and C in the November number, page 537, was erroneously inserted.

The correct scale for each is that given under the title. The other is about 12 per cent. too small.

The number on Plates XCVI and XCVII should be reversed.

Volume XXV, p. 447, fifteenth line from top, "3 400 yards" should read "400 yards."

ILLUSTRATIONS.

PLATE.	MONTH,		PAPER.	PAGE.
I-V.	(July.)	Narragansett Chimney	483	7
VI-VIII.	(do.)	Mechanical Condition of Car		
		Wheels	487	39
IX-XI.	(do.)	Water Meters	488	52
XII-XIV.	(do.)	Excessive Rainfalls	489	108
XV-XVI.	(do.)	Mountain Railways	490	124
XVII-XXV.	(August.)	Inland Sewage Disposal	491	134, 140
XXVI-XL.	(do.)	American Irrigation Engineering	492	173, 206
XLI.	(do.)	Diagram for Dimensions of	495	242
VIII VIV	13.3	Wooden Beams by Inspection	200	. 424
XLII-XLV.	(do.)	Longitudinal Bearing Systems for	496	242
LVI.	(011)	Railway Track		257
	(September.)	Yield of the Sudbury River	497	257
LVII.	(do.)	Notes on Cements, Mortars and	498	278
TWIII TWII	12-1	Concretes	200	210
LVIII-LXII.	(do.)	Neat Tests vs. Sand Tests of Ce-	499	900 900
TVIII TVVIII		ment	-	300, 302 312
LXIII-LXXVI.	(do.)	Marent Gulch Viaduct	500	
LXXVII.	(do.)	Right of Way	501	322
LXXVIII-LXXXII.	(October.)	Origin of Viaduct	503	360
LXXXIII-LXXXVI.	(do.)	Steamship and Tow Barge Effi- ciency, etc	504	384-6
LXXXVII-LXXXIX	. (do.)	Single Trap System	505	395, 402, 404
XC-XCII.	(do.)	Use of Dynamite on Ocean Bar	508	446
XCIII.	(November.)	Stresses in Bridges on Curves	509	490
XCIV-XCV.	(do.)	Dimension Stone Quarrying	510	513
XCVI-CII.	(do.)	Brazos River Harbor Improve-		
	()	ment	511	537
CIII.	(December.)	Chart of Harbor of New York	513	614
CIV.	(do.)	View of Steamer Reliance	513	596
CV-CX.	(do.)	Details of Dredging Steamer, Dump		
	,,	Scow, etc	513	614
CXI-CXVI-CXXI.	(do.)	Plates of Red Rock Cantilever		
	()	Bridge	518	696
CXVII-CXVIII.	(do.)	View of Tramway Red Rock Can-		
	()	tilever Bridge	518	686
CXIX-CXX.	(do.)	View of Machinery, Scow, Red		
	()	Rock Cantilever Bridge	518	689
CXXII.	(do.)	General View of Bridge	518	696
CXXIII-CXXVII.	(do.)	Details of Red Rock Cantilever		
	,y	Bridge	518	711